

Work Order ID 76061

76061

Page 1

Friday, November 25, 2011 9:15:00 AM

Item ID: D412-666-011

Accept

N900040100

Setup Start *NS1*

Revision ID:

Item Name: Gross Weight Towing

Stop *NS2*

Start Date: 11/4/2011 Start Qty: 1.00 *1*

Cust Item ID:

Required Date: 11/7/2011 Req'd Qty: 1.00 *1*

Customer: CU-DAR001

Reference: RMA RA111280 - RETURN

Approvals: Process Plan: MF Date: 11-11-25

Tooling:

Date:

Run Start *NR1*

QC:

Date:

SPC (Y/N):

Date:

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN D412-666	Rev C1								

100

0.00

100

QC

Quality Control

Memo

0.00

INSPECT RA 111280 D 412-666-011 X 1

KIT IS GOOD: NO TOUCH UPS NECESSARY

NEEDS NEW PAPERWORK

ID AND STOCK UNDER NEW BATCH NUMBER

110

Identify as per dwg & Stock Location: FB 121 0.00

110

Packaging

Memo

0.00

Packaging

8 u 12/05

CHG004

Copy 1

Work Order ID 76061***76061***

Page 2

Friday, November 25, 2011 9:15:00 AM

Item ID: D412-666-011

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Gross Weight Towing

Stop ***NS2***

Start Date: 11/4/2011 Start Qty: 1.00

1

Cust Item ID:

Required Date: 11/7/2011 Req'd Qty: 1.00

1

Customer: CU-DAR001

Reference: RMA RA111280

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

120

QC21- Final Inspection - Work Order Release

0.00

120

QC

Memo

0.00

Quality Control

11/12/15
ME
11-12-05